

11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244 East 11115 Montgomery, Suite B, Spokane, WA 99206-4776 9405 S.W. Nimbus Avenue, Beaverton, OR 97008-7132 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711 (425) 420-9200 X 420-9210 (509) 924-9200 X 924-9290 (503) 906-9200 FAX 906-9210

(541) 383-9310 FAX 382-7588

CHAIN OF CUSTODY REPORT

Work Order #: M106036

| CLIENT: BRISTOL | | | | | INVO | ICE TO | :BK | 45 | 101 | happen distribution, | | | | | TURN | AROUNI | O REQUES | Γ in Business | Days* |
|----------------------------------|---------------------|-------|----------|-----|--------|--------|--------|-------|---------|----------------------|----|----|---------------------------------------|-------|---|--------|-------------------|---------------------|--------------|
| REPORT TO: ANNE | KRANAWETTE | R | 47/25 | | | | | | | | | | | | | | ic & Inorganic | | |
| ADDRESS: AMCHITKI | | | | | | | | | | | | | | | 10 7 | 5 | 4 3 | 2 1 | < 1 |
| | | | | 5 | | | 1 | 21. | 0.00 | | | | | | STD. | | ım Hydrocarbo | on Analyses | a l |
| PHONE: 907-770 PROJECT NAME: AMC | FAX: | 0-(| <u> </u> | | P.O. N | UMBE | | | ALYSES | | | | | | STI | - | | | - |
| PROJECT NUMBER: 210 | TIM | | T | | | KE | (OLST) | LDANA | ALT SEC | · | | | | | 577 | OTH | | e Specify | |
| | 10 | | | | | | | | | | | | | | *************************************** | | | rd may incur Rush C | |
| SAMPLED BY: | | | 1 | | | | | | | | | | | | | T | less than standai | d may incur Rush C | _ |
| CLIENT SAMPLE | SAMPLING | 8 | Meta | | | | | - | | | | | | | MATRIX | # OF | | | NCA WO |
| IDENTIFICATION | DATE/TIME | 8 | 5 | | | | | | | | | | | | (W, S, O) | CONT. | COM | IMENTS | ID |
| 1. OLAMLAOIMI | 6/12/01/1745 | X | X | | | | | | | | | | | | 5 | 2 | | | |
| 2. | | | | | | | | | | | | | | | | | | | |
| 3. Com 8/7/01 | | - | | | | | | | | | | | | | | | | | |
| 3. Cm 8/7/01 4. charge JU 12 | | | | . , | | | | | | | | | | | | | | | |
| 5. | 4 | | | | | - | | | | | .* | | | J.s. | | | | | |
| 6. | | | - | | | | | | | | | | | | | | | | |
| 7. | | | | | | | 7.7 | | | | | | · · · · · · · · · · · · · · · · · · · | | | | | | |
| 8. | | | | | | | | 18 | | | | | | | | | , | | |
| 9. | | | | | | , y., | | , | | | | | * | 1 | | | | | |
| 10. | | | | | | | | | | , | | | | | | | | | |
| 11. | | | | | | | | | | | | | | | | | 1, | | |
| 12. | | | | | | | | | | , | | | | | 1, | | | *** | |
| 13. | | | | | | | | | | | | | | | | | | | |
| 14. | | | | | | | | | | | | | | | | | | | |
| 15. | 110/0 | | | | | , | | | | | - | | 1 | | | | | | |
| RELINQUISHED BY: | Med | 2 0 | · | | DATE: | 6112 | 101 | RECEI | VED BY | | an | 03 | ode | e n | 1) | NC | A | DATE | 3: ***** |
| PRINT NAME: Chali harsh | FIRM: | SK1 | 010 | _ | TIME: | 183 | 6 | PRINT | NAME: | | / | 2 | raio | 1 121 | ad JEIRM: | 100 | H | TIME | 3: · |
| RELINQUISHED BY: | | | | | DATE: | | | | VED BY | : | / | | | | | | | DATE | |
| PRINT NAME: | FIRM: | | | | TIME: | | | PRINT | NAME: | | | | | | FIRM: | | | TIME | š: |
| ADDITIONAL REMARKS: | ofor Metals A | | 1 | | | | | | | | | | | | | | TE | MP: | 9 8 |
| COCREV 3/99 X Sec SA | 11- Los WG +10-12 V | 530 C | ha (| LA | Joon | | | | | | | | | | | | 1 | PAG | E OF |



425.420.9200 fax 425.420.9210

Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776

509.924.9200 fax 509.924.9290

Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132 503.906.9200 fax 503.906.9210

Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711 541.383.9310 fax 541.382.7588

6 December, 2001

Anne Kranawetter Bristol Environmental & Engineering 2000 W International Airport C#1 Anchorage, AK 99502-1116

RE: Amchitka

Enclosed are the results of analyses for samples received by the laboratory on 06/12/01 18:35. If you have any questions concerning this report, please feel free to contact me.

This report was recreated from a previously issued final report in order to provide an electronic copy. The final report used for these electronic copies may have been previously issued as an amended report due to client requested changes to sample names, etc. No data has changed since submission of the previously issued final, or amended, report.

Sincerely,

Stephen Wilson

Environmental Group Leader

1112

Work Orders included in this report:

M106036



Reported:

425.420.9200 fax 425.420.9210

Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776

509.924.9200 fax 509.924.9290 **Portland** 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132

503.906.9200 fax 503.906.9210

Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711 541.383.9310 fax 541.382.7588

Bristol Environmental & Engineering Project: Amchitka 2000 W International Airport C#1 Project Number: 21090

Project Manager: Anne Kranawetter 10/25/01 01:08

ANALYTICAL REPORT FOR SAMPLES

Sample ID Laboratory ID Matrix Date Sampled Date Received

01AMLA01MI-B M106036-01 Soil 06/12/01 17:45 06/12/01 18:35

C.OC. #78

Anchorage, AK 99502-1116

North Creek Analytical - Mobile Lab



Anchorage, AK 99502-1116

Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-9223 425.420.9200 fax 425.420.9210

Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776

509.924.9200 fax 509.924.9290

Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132 503.906.9200 fax 503.906.9210

Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711

541.383.9310 fax 541.382.7588

Bristol Environmental & Engineering Project: Amchitka 2000 W International Airport C#1 Project Number: 21090

Reported: 10/25/01 01:08

Project Manager: Anne Kranawetter

Polychlorinated Biphenyls per EPA Method 8082 North Creek Analytical - Mobile Lab

| Analyte | Result | Reporting Limit | Units | Dilution | Method | Prepared | Analyzed | Batch | Notes |
|------------------------------------|--------|--------------------|-----------|----------|--------------|------------|---------------|---------|-------|
| 01AMLA01MI-B (M106036-01) Soil | | | | | Sampled: 06/ | 12/01 Rece | eived: 06/12/ | 01 | |
| Aroclor 1016 | ND | 167 | ug/kg dry | 1 | EPA 8082 | 06/13/01 | 06/14/01 | 0106047 | |
| Aroclor 1221 | ND | 334 | " | " | " | " | " | " | |
| Aroclor 1232 | ND | 167 | " | " | " | " | " | " | |
| Aroclor 1242 | ND | 167 | " | " | " | " | " | " | |
| Aroclor 1248 | ND | 167 | " | " | " | " | " | " | |
| Aroclor 1254 | ND | 167 | " | " | " | " | " | " | |
| Aroclor 1260 | ND | 167 | " | " | " | " | " | " | |
| Surr: 2,4,5,6-Tetrachloro-m-xylene | 128 % | 55-130 | | | | | | · | |
| Surr: Decachlorobiphenyl | 126 % | 55-130 | | | | | | | |

North Creek Analytical - Mobile Lab



Anchorage, AK 99502-1116

Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-9223

425.420.9200 fax 425.420.9210

Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776

509.924.9200 fax 509.924.9290

Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132

503.906.9200 fax 503.906.9210 **Bend** 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711 541.383.9310 fax 541.382.7588

Bristol Environmental & Engineering Project: Amchitka 2000 W International Airport C#1 Project Number: 21090

Reported: 10/25/01 01:08

Project Manager: Anne Kranawetter

Total Metals per EPA 6000/7000 Series Methods North Creek Analytical - Mobile Lab

| Analyte | Result | Reporting Limit | Units | Dilution | Method | Prepared | Analyzed | Batch | Notes |
|-----------------------------------|--------|--------------------|-----------|----------|--------------|------------|---------------|---------|-------|
| 01AMLA01MI-B (M106036-01) Soil | | | | | Sampled: 06/ | 12/01 Rece | eived: 06/12/ | /01 | |
| Arsenic | 3.35 | 0.250 | mg/kg dry | 1 | EPA 6020 | 06/13/01 | 06/14/01 | 0106044 | A-01 |
| Cadmium | ND | 0.250 | " | " | " | " | " | " | |
| Chromium | 13.0 | 0.250 | " | " | " | " | " | " | |
| Lead | 4.27 | 0.250 | " | " | " | " | " | " | |
| Selenium | 0.598 | 0.250 | " | " | " | " | " | " | |
| Silver | ND | 0.250 | " | " | " | " | " | " | |
| 01AMLA01MI-B (M106036-01RE1) Soil | | | | | Sampled: 06/ | 12/01 Rece | eived: 06/12/ | 01 | |
| Mercury | 0.0191 | 0.00500 | mg/kg dry | 1 | EPA 1631 | 06/24/01 | 06/25/01 | 0106082 | |

North Creek Analytical - Mobile Lab



2000 W International Airport C#1

Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-9223

Reported:

425.420.9200 fax 425.420.9210

Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776

509.924.9200 fax 509.924.9290

Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132

503.906.9200 fax 503.906.9210 **Bend** 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711 541.383.9310 fax 541.382.7588

Bristol Environmental & Engineering Project: Amchitka

Anchorage, AK 99502-1116 Project Manager: Anne Kranawetter 10/25/01 01:08

Project Number: 21090

Physical Parameters per APHA/ASTM/EPA Methods North Creek Analytical - Mobile Lab

| Analyte | Result | Reporting Limit | Units | Dilution | Method | Prepared | Analyzed | Batch | Notes |
|--------------------------------|--------|--------------------|----------|----------|--------------|-------------|--------------|---------|-------|
| 01AMLA01MI-B (M106036-01) Soil | | | | | Sampled: 06/ | /12/01 Rece | ived: 06/12/ | 01 | |
| % Solids | 75.3 | 0.0100% | by Weigh | t 1 | Gravimetric | 06/13/01 | 06/14/01 | 0106046 | |

North Creek Analytical - Mobile Lab



425.420.9200 fax 425.420.9210

Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776

509.924.9200 fax 509.924.9290

Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132

503.906.9200 fax 503.906.9210

Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711

541.383.9310 fax 541.382.7588

Bristol Environmental & Engineering 2000 W International Airport C#1

Project: Amchitka
Project Number: 21090

Reported: 10/25/01 01:08

Anchorage, AK 99502-1116

Project Manager: Anne Kranawetter

Polychlorinated Biphenyls per EPA Method 8082 - Quality Control

North Creek Analytical - Mobile Lab

| | | Reporting | | Spike | Source | | %REC | | RPD | |
|---------|--------|-----------|-------|-------|--------|------|--------|-----|-------|-------|
| Analyte | Result | Limit | Units | Level | Result | %REC | Limits | RPD | Limit | Notes |

| Blank (0106047-BLK1) | | | | Prepared | 1: 06/13/0 | 1 Analyz | zed: 06/14/0 | 1 | | |
|------------------------------------|------|-----------|-----------|----------|------------|----------|--------------|------|----|------|
| Aroclor 1016 | ND | 167 | ug/kg wet | • | | | | | | |
| Aroclor 1221 | ND | 334 | " | | | | | | | |
| Aroclor 1232 | ND | 167 | " | | | | | | | |
| Aroclor 1242 | ND | 167 | " | | | | | | | |
| Aroclor 1248 | ND | 167 | " | | | | | | | |
| Aroclor 1254 | ND | 167 | " | | | | | | | |
| Aroclor 1260 | ND | 167 | " | | | | | | | |
| Surr: 2,4,5,6-Tetrachloro-m-xylene | 26.2 | | " | 66.7 | | 39.3 | 55-130 | | | A-02 |
| Surr: Decachlorobiphenyl | 26.2 | | " | 66.7 | | 39.3 | 55-130 | | | A-02 |
| LCS (0106047-BS1) | | | | Prepared | 1: 06/13/0 | 1 Analyz | zed: 06/14/0 | 1 | | |
| Aroclor 1254 | 593 | 167 | ug/kg wet | 667 | | 88.9 | 55-130 | | | |
| Surr: 2,4,5,6-Tetrachloro-m-xylene | 83.0 | | " | 66.7 | | 124 | 55-130 | | | |
| Surr: Decachlorobiphenyl | 89.9 | | " | 66.7 | | 135 | 55-130 | | | S-08 |
| Matrix Spike (0106047-MS1) | Sour | ce: M1060 | 036-01 | Prepared | 1: 06/13/0 | 1 Analyz | zed: 06/14/0 | 1 | | |
| Aroclor 1254 | 1980 | 339 | ug/kg dry | 1800 | ND | 110 | 55-130 | | | |
| Surr: 2,4,5,6-Tetrachloro-m-xylene | 267 | | " | 180 | | 148 | 55-130 | | | S-08 |
| Surr: Decachlorobiphenyl | 279 | | " | 180 | | 155 | 55-130 | | | S-08 |
| Matrix Spike Dup (0106047-MSD1) | Sour | ce: M1060 | 036-01 | Prepared | 1: 06/13/0 | 1 Analyz | zed: 06/14/0 | 1 | | |
| Aroclor 1254 | 1960 | 339 | ug/kg dry | 1800 | ND | 109 | 55-130 | 1.02 | 40 | |
| Surr: 2,4,5,6-Tetrachloro-m-xylene | 266 | | " | 180 | | 148 | 55-130 | | | S-08 |
| Surr: Decachlorobiphenyl | 274 | | " | 180 | | 152 | 55-130 | | | S-08 |

North Creek Analytical - Mobile Lab



425.420.9200 fax 425.420.9210

Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776

509.924.9200 fax 509.924.9290

Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132

503.906.9200 fax 503.906.9210 **Bend** 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711 541.383.9310 fax 541.382.7588

Bristol Environmental & Engineering Project: Amchitka 2000 W International Airport C#1 Project Number: 21090

Reported:

Anchorage, AK 99502-1116 Project Manager: Anne Kranawetter

10/25/01 01:08

Total Metals per EPA 6000/7000 Series Methods - Quality Control

North Creek Analytical - Mobile Lab Reporting Spike Source %REC RPD

| | | Reporting | | Spike | Source | | %REC | | RPD | |
|-----------------------------------|--------|------------|-----------|---------|-------------|----------|-------------|-------|-------|-------|
| Analyte | Result | Limit | Units | Level | Result | %REC | Limits | RPD | Limit | Notes |
| Batch 0106044 - EPA 3050 | | | | | | | | | | |
| Blank (0106044-BLK1) | | | | Prepare | ed: 06/13/0 | 1 Analyz | ed: 06/14/0 |)1 | | |
| Arsenic | ND | 0.250 | mg/kg wet | | | | | | | |
| Cadmium | ND | 0.250 | " | | | | | | | |
| Chromium | ND | 0.250 | " | | | | | | | |
| Lead | ND | 0.250 | " | | | | | | | |
| Selenium | ND | 0.250 | " | | | | | | | |
| Silver | ND | 0.250 | " | | | | | | | |
| LCS (0106044-BS1) | | | | Prepare | ed: 06/13/0 | 1 Analyz | ed: 06/14/0 |)1 | | |
| Arsenic | 10.8 | 2.50 | mg/kg wet | 10.0 | | 108 | 80-120 | | | A-01 |
| Cadmium | 10.1 | 2.50 | " | 10.0 | | 101 | 80-120 | | | |
| Chromium | 10.5 | 2.50 | " | 10.0 | | 105 | 80-120 | | | |
| Lead | 10.8 | 2.50 | " | 10.0 | | 108 | 80-120 | | | |
| Selenium | 10.2 | 2.50 | " | 10.0 | | 102 | 80-120 | | | |
| Silver | 9.88 | 2.50 | " | 10.0 | | 98.8 | 80-120 | | | |
| Duplicate (0106044-DUP1) | Sou | rce: M1060 | 36-01 | Prepare | ed: 06/13/0 | 1 Analyz | ed: 06/14/0 |)1 | | |
| Arsenic | 3.00 | 0.250 | mg/kg dry | | 3.35 | | | 11.0 | 40 | A-01 |
| Cadmium | ND | 0.250 | " | | ND | | | | 40 | |
| Chromium | 12.2 | 0.250 | " | | 13.0 | | | 6.35 | 40 | |
| Lead | 4.65 | 0.250 | " | | 4.27 | | | 8.52 | 40 | |
| Selenium | 0.597 | 0.250 | " | | 0.598 | | | 0.167 | 40 | |
| Silver | ND | 0.250 | " | | ND | | | | 40 | |
| Matrix Spike (0106044-MS1) | Sou | rce: M1060 | 36-01 | Prepare | ed: 06/13/0 | 1 Analyz | ed: 06/14/0 |)1 | | |
| Arsenic | 18.5 | 2.50 | mg/kg dry | 13.3 | 3.35 | 114 | 75-125 | | | A-01 |
| Cadmium | 14.3 | 2.50 | " | 13.3 | ND | 108 | 75-125 | | | |
| Chromium | 28.2 | 2.50 | " | 13.3 | 13.0 | 114 | 75-125 | | | |
| Lead | 20.0 | 2.50 | " | 13.3 | 4.27 | 118 | 75-125 | | | |
| Selenium | 13.9 | 2.50 | " | 13.3 | ND | 100 | 75-125 | | | |
| Silver | 13.5 | 2.50 | " | 13.3 | ND | 102 | 75-125 | | | |
| | | | | | | | | | | |

North Creek Analytical - Mobile Lab



425.420.9200 fax 425.420.9210

Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776 509.924.9200 fax 509.924.9290

Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132

503.906.9200 fax 503.906.9210 **Bend** 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711

541.383.9310 fax 541.382.7588

Bristol Environmental & Engineering

2000 W International Airport C#1

Anchorage, AK 99502-1116

Project: Amchitka
Project Number: 21090

Reported: 10/25/01 01:08

Project Manager: Anne Kranawetter

Total Metals per EPA 6000/7000 Series Methods - Quality Control

North Creek Analytical - Mobile Lab

| | 11010 | i Cicci i inai | | N 110 1100 | • | | | | |
|----------------------------|--------|------------------|------------|-------------|----------|-------------|------|-------|-------|
| | | Reporting | Spike | Source | | %REC | | RPD | |
| Analyte | Result | Limit Unit | Level | Result | %REC | Limits | RPD | Limit | Notes |
| Batch 0106082 - EPA 1631 | | | | | | | | | |
| Blank (0106082-BLK1) | | | Prepare | ed: 06/24/0 | 1 Analyz | ed: 06/25/0 |)1 | | |
| Mercury | ND | 0.00500 mg/kg v | vet | | | | | | |
| LCS (0106082-BS1) | | | Prepare | ed: 06/24/0 | 1 Analyz | ed: 06/25/0 |)1 | | |
| Mercury | 0.0112 | 0.00500 mg/kg v | vet 0.0100 | | 112 | 85-115 | | | |
| Duplicate (0106082-DUP1) | Sou | rce: M106036-01F | E1 Prepare | ed: 06/24/0 | 1 Analyz | ed: 06/25/0 |)1 | | |
| Mercury | 0.0224 | 0.00500 mg/kg | dry | 0.0191 | | | 15.9 | 20 | |
| Matrix Spike (0106082-MS1) | Sou | rce: M106036-01F | E1 Prepare | ed: 06/24/0 | 1 Analyz | ed: 06/25/0 |)1 | | |
| Mercury | 0.0328 | 0.00500 mg/kg | dry 0.0133 | 0.0191 | 103 | 75-125 | | | |

North Creek Analytical - Mobile Lab



425.420.9200 fax 425.420.9210

Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776

509.924.9200 fax 509.924.9290

Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132

503.906.9200 fax 503.906.9210

Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711

541.383.9310 fax 541.382.7588

Bristol Environmental & Engineering Project: Amchitka 2000 W International Airport C#1 Project Number: 21090

Reported: 10/25/01 01:08

Project Manager: Anne Kranawetter

Notes and Definitions

A-01 The ICV had 112 % recovery, indicating potential high bias.

A-02 Surrogate spike recoveries were low and out of control limits due to a leak that occurred during automated solvent extraction.

Sample integrity has not been compromised.

S-08 Surrogate recovery is above control limits. Since no analytes were detected in the sample, the quality of the data has not been

affected.

Anchorage, AK 99502-1116

DET Analyte DETECTED

ND Analyte NOT DETECTED at or above the reporting limit

NR Not Reported

dry Sample results reported on a dry weight basis. MRLs are adjusted if %Solids are less than 50%.

wet Sample results reported on a wet weight basis (as received)

RPD Relative Percent Difference

North Creek Analytical - Mobile Lab

Items for Project Manager Review

| LabNumber | Analysis | Analyte | Exception |
|--------------|---------------------|------------------------------|---|
| | | | Default Report (not modified) |
| | | | Report recreated from: \\sisters\elmnt\Report\M106036 FINAL 10 25 01 0108.mdb |
| 0106044-BS1 | As Total ICPMS 6020 | Arsenic | A-01 |
| 0106044-DUP1 | As Total ICPMS 6020 | Arsenic | A-01 |
| 0106044-MS1 | As Total ICPMS 6020 | Arsenic | A-01 |
| 0106047-BLK1 | 8082 PCB | Decachlorobiphenyl | A-02 |
| 0106047-BLK1 | 8082 PCB | 2,4,5,6-Tetrachloro-m-xylene | A-02 |
| 0106047-BLK1 | 8082 PCB | 2,4,5,6-Tetrachloro-m-xylene | Exceeds lower control limit |
| 0106047-BLK1 | 8082 PCB | Decachlorobiphenyl | Exceeds lower control limit |
| 0106047-BS1 | 8082 PCB | Decachlorobiphenyl | S-08 |
| 0106047-BS1 | 8082 PCB | Decachlorobiphenyl | Exceeds upper control limit |
| 0106047-MS1 | 8082 PCB | Decachlorobiphenyl | S-08 |
| 0106047-MS1 | 8082 PCB | 2,4,5,6-Tetrachloro-m-xylene | S-08 |
| 0106047-MS1 | 8082 PCB | Decachlorobiphenyl | Exceeds upper control limit |
| 0106047-MS1 | 8082 PCB | 2,4,5,6-Tetrachloro-m-xylene | Exceeds upper control limit |
| 0106047-MSD1 | 8082 PCB | Decachlorobiphenyl | S-08 |
| 0106047-MSD1 | 8082 PCB | Decachlorobiphenyl | Exceeds upper control limit |
| 0106047-MSD1 | 8082 PCB | 2,4,5,6-Tetrachloro-m-xylene | S-08 |
| 0106047-MSD1 | 8082 PCB | 2,4,5,6-Tetrachloro-m-xylene | Exceeds upper control limit |
| M106036-01 | As Total ICPMS 6020 | Arsenic | A-01 |